

Howard County Traffic Signal Inspection Summary Report:

Signal Number: 076
Location: Harpers Farm Rd. at Willow Bottom Rd.
Inspection Date: April 12, 2018

Inspection Overall Score: 13

Significant Findings:

Poles are in overall good condition. Paint coating is in good condition.



Maintenance Issues:

Crosswalks and stop lines are in poor condition.