## **Howard County Traffic Signal Inspection Summary Report:**

**Signal Number:** 079

**Location:** Rogers Ave. at Orchard Ridge/Patapsco Valley

**Inspection Date:** June 6, 2018

**Inspection Overall Score:** 11

## Significant Findings:

Poles are in overall good condition.











## Maintenance Issues:

All four structures have loose tightening nuts.

Overgrowth needs to be trimmed from cabinet to improve access.

SE and SW Corners – overgrowth needs to be trimmed from around structures.



