

## Howard County Traffic Signal Inspection Summary Report:

**Signal Number:** 080  
**Location:** Robert Fulton at Solar Walk/Snowden Square  
**Inspection Date:** April 23, 2018

**Inspection Overall Score:** 28

### Significant Findings:

Poles in overall fair condition. Paint coating in poor condition, with large areas of coating failure and surface rust beginning to form.



### Maintenance Issues:

Damaged electrical service conduit.  
Hand holes retaining water.  
Trip hazard – hand hole collar above grade.

