

Howard County Traffic Signal Inspection Summary Report:

Signal Number: 083
Location: Guilford Rd. at Sanner Rd.
Inspection Date: May 2, 2018

Inspection Overall Score: 8

Significant Findings:

Poles are in overall good condition.



Maintenance Issues:

Stop lines in fair condition.
Cabinet door lock needs lubrication.