

## Howard County Traffic Signal Inspection Summary Report:

**Signal Number:** 086  
**Location:** Great Star Drive at Summer Sunrise  
**Inspection Date:** May 24, 2018

**Inspection Overall Score:** 16

### Significant Findings:

Poles are in overall good condition. Paint coating is in good condition.



### Maintenance Issues:

SW Corner – damaged tactile warning pad.  
Two shifted hand hole lids.  
Overgrowth should be trimmed from around structures.

