Howard County Traffic Signal Inspection Summary Report:

Signal Number: 089

Location: Columbia Gateway Dr. at Samuel Morse Dr.

Inspection Date: April 23, 2018

Inspection Overall Score: 16

Significant Findings:

Poles are in overall good condition. Paint coating is in good condition.







Maintenance Issues:

Crosswalk and stop lines in fair condition. Several hand holes are retaining water.

