

## Howard County Traffic Signal Inspection Summary Report:

**Signal Number:** 094  
**Location:** McGaw Rd. at Sanford Rd.  
**Inspection Date:** May 2, 2018

**Inspection Overall Score:** 11

### Significant Findings:

Newer signal.



### Maintenance Issues:

N/A