<u>Howard County Traffic Signal Inspection Field Survey Rating Form - Page 1: Structures</u>

Signal Number:		22	Location:	Little Patuxent Pkwy. at Columbia Rd.		
Date:		/2018	Inspected I	Sv: WH/BM	Checked By:	

STRUCTURES:	POINTS	SCORE			
Signal Age: 0-10 yrs: 0 pts. 11-20 yes: 5 pts. >20 yrs: 10 pts.	0-10	10			
Design Type: (mast-arm = 0 pts, span wire = 5	pts) 0-5	0			
Pole Type: (painted = 5 pts, galvanized = 0	pts) 0-5	5			
General condition of the poles: (good = 0 pts, fair = 5 pts, poor = 10	pts) 0-10	5			
Paint coating condition: (good = 0 pts, fair = 5 pts, poor = 10	pts) 0-10	5			
Any abnormal bending or pole rake? (moderate = 5 pts, severe = 10	pts) 0-10	0			
Pole back guys in use? (1 back guy = 3 pts, 2 back guys = 5 pts, 3 or more back guys = 10	pts) 0-10	0			
Any abnormal bending or sagging of the mast arms? (yes = 5 pts, no = 0	pts) 0-5	0			
Any signs or rust or corrosion at or near the mast arm mounting plates? (yes = 5 pts, no = 0 pts					
Any signs of rust on the span wires? (surface area: 25% or less = 5 pts, 25%-50% = 10 pts, greater than 50% = 15	pts) 0-15	0			
Any abnormal sagging of the span wires? (1 span = 5pts, 2 or more spans = 10		0			
Any span wire splices? (1 splice = 5 pts, 2 splices = 10 pts, 3 or more splices = 15	pts) 0-15	0			
Any signs of erosion around any of the pole bases? (yes = 5 pts, $no = 0$	pts) 0-5	0			
Base plate mounted directly to foundation with no leveling nuts? (yes = 5 pts, no = 0		0			
Rust or corrosion on the base plate, anchor bolts, or nuts? (severe 25 pts, moderate 15 pts, light 5 pts, no 0	pts) 0-25	15			
s the pole base welded steel or cast iron? (cast iron = 10	pts) 0-10	0			
Any signs of cracking at or near base plate welds? (10 pts any signs of crack		0			
Base plates buried? (yes + 10 pts, no = 0	pts) 0-10	0			
Any exposed rebar or abnormal exposure of the anchor bolts? (yes = 5 pts, no = 0		0			
Any abnormal cracking or spalling of concrete on any of the pole foundations? (moderate = 3 pts, severe = 5	pts) 0-5	0			
OTHER:					
Any apparent violations of the Maryland High Voltage Act? (yes = 10		0			
Any equipment obstructions to walking or biking paths? (1 obstruction = 1 pt, 2 obstructions = 3 pts, 3 or more = 5		0			
Cabinet conduit capacity: (Below = 0 pt, At = 3 pts, Above = 5	· · ·	3			
Overall condition of the hand boxes: (Good = 0 pt, Fair = 3 pts, Poor = 5		0			
Conduit fill capacity in hand boxes: (Below = 0 pts, At = 3 pts, Above = 5		3			
General condition of the electrical service: (Good = 0 pts, Fair = 3 pts, Poor = 5	pts) 0-5	0			
OVERALL SCORE:	_	46			