HO-557
Mount Misery
Ellicott City
Private

Mount Misery faces east on the west side of Hill Street, before it descends a steep hill south and turns north on Merryman Street.

It is a four bay wide, two bay deep, two-and-a-half story high, gabled roof (running north-south) granite block house, resting on a granite block foundation and set into the slope of a steep hill, with wide brick chimneys set into its north and south walls.

The north wall of this stone house connects to the south wall of another three bay wide, two bay deep, two story high, gabled roof (running north-south) granite block house, resting on a stone foundation, with wide brick central chimney inset into its north wall, set back farther westward into the slope of the hill.

The east facade of the building features vertically aligned and proportionally scaled fenestration, with two central bay, rectangular entrance doors, surmounted by four light transoms (that in the south central bay now holds only one light, but features the original pegged window frames), and flat stone lintels. These windows are double-hung, retaining their original, pegged mortise and tenon sashes, but holding six-over-one lights on the south half of the house and six-over-six lights on the north half. Windows are underlined by flat wooden lintels, and decorated with shutters.

Two gabled roof, dormer windows are placed in the roofline at this elevation. They hold rectangular windows, flanked by fluted pilasters. The window on the south side holds one-over-one lights and that on the north side six-over-six lights. Excellent stone work is exemplified by the fine stone quoining and flat stone lintels surmounting the doors and windows, as well as the choice of squarely cut stones for the east facade.

Two stone retaining walls have been constructed along the east elevation, one around the southeast corner of the building, and the other constructed along the west side of Hill Street as it slopes northward up the hill. Still another stone retaining wall runs along the west elevation of the building, creating a patio area west of the house.

The east facade of the frame appendage, attached to the south bay of the neighbors house, holds a rectangular, one light, foundation entrance door, surmounted by a two light transom, with a six-over-six light, rectangular window placed along its south side. The first floor holds a tripartite window, composed of a rectangular, three-over-three light window, flanked by small, one-over-one light windows. The third floor, actually the second floor of the neighboring stone house, holds a rectangular, six-over-six light window.

A one story high, hipped roof, open porch held by two square, wooden posts and a pilaster, and constructed on the stone retaining wall, runs along the entire east elevation at the neighboring stone house, enclosed on the south bay, forming the frame appendage just described,

A two story high, shed roofed, open porch, enclosed in its south bay has been constructed along the west wall of the neighboring stone house. A retaining wall constructed deep into the slope of the land creates a first floor patio.

This property was a part of the Real Estate of George Ellicott, which was transferred, in part, to Sarah R. Talbott in 1896.

## MARYLAND HISTORICAL TRUST

# INVENTORY FORM FOR STATE HISTORIC SITES SURVEY

NAME				
HISTORIC	Mount Misery			
AND/OR COMMON				
LOCATION	J			
STREET & NUMBER	8469 Hill Stree	t		
CITY, TOWN E1:	licott City	VICINITY OF	CONGRESSIONAL DISTRICT  6th	
STATE Mai	ryland		county Howard	
CLASSIFIC				<del></del>
CATEGORY	CATEGORY OWNERSHIP STATUS		PRESENT USE	
DISTRICT X_BUILDING(S)STRUCTURESITEOBJECT	PUBLIC XPRIVATEBOTH PUBLIC ACQUISITIONIN PROCESS	X_OCCUPIED  _UNOCCUPIED  _WORK IN PROGRESS  ACCESSIBLE  X_YES: RESTRICTED  _YES: UNRESTRICTED	AGRICULTURECOMMERCIALEDUCATIONALENTERTAINMENTGOVERNMENTINDUSTRIAL	MUSEUMPARK  X_PRIVATE RESIDENRELIGIOUSSCIENTIFICTRANSPORTATIO
	BEING CONSIDERED	NO	MILITARY	_OTHER:
	F PROPERTY			
NAME	Mr. Guy W. Hag	er 	Telephone #: 4	61-2499
STREET & NUMBER	8469 Hill Stre	et		
CITY, TOWN E13	licott City	VICINITY OF	state, z Maryland 21043	ip code
LOCATION COURTHOUSE. REGISTRY OF DEEDS	Tax Map 25-A, p.  Hall of Records		Liber #: 246 Folio #: 87	
STREET & NUMBER	Howard County Co	urt House		
CITY, TOWN	Ellicott City		STATE M	aryland
TITLE	NTATION IN EXIST			
	<del></del>			
DATE 1978-		FEDERAL	XSTATE _COUNTY _LOCAL	
DATE			XSTATECOUNTYLOCAL	



CONDITION

CHECK ONE

CHECK ONE

SXCELLENT

\_FAIR

\_\_DETERIORATED

\_UNEXPOSED

\_\_UNALTERED

XORIGINAL SITE
\_\_MOVED DATE\_\_\_

### DESCRIBE THE PRESENT AND ORIGINAL (IF KNOWN) PHYSICAL APPEARANCE

Mount Misery faces east on the west side of Hill Street, before it descends a steep hill south and turns north on to Merryman Street.

It is a four bay wide, two bay deep, two-and-a-half story high, gabled roof (running north-south) granite block house, resting on a grantie block foundation and set into the slope of a steep hill, with wide, brick chimneys set into its north and south walls.

The north wall of this stone house connects to the south wall of another three bay wide, two bay deep, two story high, gabled roof (running north-south) granite block house, resting on a stone foundation, with wide, brick, central chimney inset into its north wall, set back farther westward into the slope of the hill.

#### EAST ELEVATION

The east facade of the building features vertically aligned and proportionally scaled fenestration, with two central bay, rectangular entrance doors, surmounted by four light transoms (that in the south central bay now holds only one light, but features the original pegged window frames), and flat stone lintels. These windows are double-hung, retaining their original, pegged mortise and tenon sashes, but holding six-over-one lights on the south half of the house and six-over-six lights on the north half. Windows are underlined by flat wooden lintels, and decorated with shutters.

Two gabled roof, dormer windows are placed in the roofline at this elevation. They hold rectangular windows, flanked by fluted pilasters. The window on the south side holds one-over-one lights and that on the north side six-over-six lights. Excellent stone work is exemplified by the fine stone quoining and flat stone lintels, surmounting the doors and windows, as well as the choice of squarely cut stones for the east facade.

Two stone retaining walls have been constructed along the east elevation, one around the southeast corner of the building, and the other constructed along the west side of Hill Street as it slopes northward up the hill. Still another stone retaining wall runs along the west elevation of the building, creating a patio area west of the house.

The east facade of the frame appendage attached to the south bay of the neighbor's house, holds a rectangular, one light, foundation entrance door, surmounted by a two light transom, with a six-over-six light, rectangular window placed along its south side. The first floor holds a tripartite window, composed of a rectangular, three-over-three light window, flanked by small, one-over-one light windows. The third floor, actually the second floor of the neighboring stone house, holds a

CONTINUE ON SEPARATE SHEET IF NECESSARY

Mount Misery Page 2 of 4

HO-557
Ellicott City Quad
District 2

rectangular, six-over-six light window.

A one story high, hipped roof, open porch, held by two square, wooden posts and a pilaster, and constructed on the stone retaining wall, runs along the entire east elevation of the neighboring stone house, enclosed on the south bay, forming the frame appendage just described, upon which was later added a second floor. The east wall of the stone house holds two first and second floor windows, similar to the others, but underlined by projecting stone sills, in its central and east bays.

#### THE NORTH ELEVATION

The north elevation of Mount Misery is partially covered by its neighboring, early nineteenth century, stone house, constructed along the north wall of Mount Misery, but set back from it. (Its brick eave line extension on its north elevation reveals this fact.) This stone house. coupled with its frame, east extension completely covers the north wall of Mount Misery. The north wall of this neighbor holds no first and second floor apertures, such as we find on the south elevation of Mount Misery, but two rectangular attic windows, which hold double-hung sashes, holding four-over-two lights, underlined by projecting wooden sills. Those same attic windows on the south elevation of Mount Misery were removed and now hold one-over-one light, storm windows. Mr. Hager, owner of Mount Misery, plans to install windows, similar to the original, found on the north wall of the neighboring stone house.

The north elevation of the frame appendage, added to the south bay of the neighboring stone house, holds an exceptionally fine, first floor, rectangular, open Bible and cross paneled entrance door, flanked by three vertical side lights and surmounted by a handsome seven light transom. This appendage has been mentioned in conjunction with the east elevation and covers the south bay of the three bay wide, one room deep, two story high, neighboring stone house.

#### THE SOUTH ELEVATION

The south elevation of Mount Misery originally held two, rectangular, entrance doors, surmounted by flat stone lintels. That on the east bay has been made into a window.

The second floor holds a west bay, rectangular, window with double-hung sash, holding one-over-one lights and a rectangular, two light second floor, blocked, entrance door in its east bay. Two rectangular, attic windows, holding one-over-one light, storm windows, rest above.

The south elevation of the two story high, frame, shed roofed, appendage, constructed along the west wall of the house, holds a rectangular, first, floor kitchen entrance, with a picture window placed east of it. A one story high, shed roofed, shingled, kitchen porch runs along the south wall of the kitchen appendage.

HO-557
Ellicott City Quad
District 2

#### THE WEST ELEVATION

The west elevation, though not as handsome and symetrical as its east facade, is its most interesting. Here one can visualize the manner in which the building was contructed, cutting deeply into this steep slope, which rises sharply from the west side of Hill Street.

Two, two story high, shed roofed, frame appendages cover the west wall of the stone house and at this west wall level, their second floors provide two, ground level entrances. A small additional, shed roofed appendage has been constructed on the south side of Mount Misery, providing a furnace room on the ground level and a bath on its second level.

A two story high, shed roofed, open porch, enclosed in its south bay has been constructed along the west wall of the neighboring stone house. A retaining wall, constructed deep into the slope of land, creates a first floor patio. A wooden bridge, flanked by a wooden railing, crosses the patio of the neighboring stone house and leads to the second floor of the open porch.

#### INTERIOR

The ground floor levels of the two houses, which become actual basement foundations on the west elevation, have generally been used for storage and/or as a service function, while the living quarters and public rooms were located on the second floor. This second floor on the west elevation, actually becomes a ground floor.

#### SOUTH HALF OF MOUNT MISERY

The south half of Mount Misery, now owned by Mr. Guy Hager, has undergone extensive renovation and gutting. The ground floor of the stone house is divided into two rooms, with a fireplace placed east of center on its south wall. The plaster on the west interior wall of the house has been removed to reveal the original stone work.

Plans are being made to remove the dividing wall, which creates the two rooms and to establish one large room, with the main entrance placed on the south elevation of the stone house. It is believed that this partition is not original to the building which features brick interior walls. The present hardwood floors are in the process of being removed to reveal the original tongue-and-groove, random width, pine floors of the house. The first and second floor staircases, (running east-west) along the north wall of the middle, brick partition wall of the building, have been opened up by previous owners. It is Mr. Hager's plan to restore them to their original character, enclosing them and perhaps even installing entrance doors to the staircases. Some of the original wainscotting used for that purpose has been found on the premises. The ground floor staircase retains an interesting, small, cross paneled, rectangular, closet door and features fine, random width wainscotting, recently uncovered by Mr. Hager. Wide baseboards are an

additional feature of both the first and second floors.

The first floor, of the two story high, shed roofed appendage holds a modern kitchen, while its second floor holds a den or family room.

The second floor of the stone section of the house features fine woodwork in its door and window frames, composed of fluted pilasters and lintels, joined by square corners, decorated with rosettes.

The east half of the second floor holds a large master bedroom, which may originally have been the drawing room for the house.

The plaster, covering the brick fireplace on the south wall of the master bedroom, has been totally removed, revealing a stretcher brick, flat arched lintel. The room features two east windows and a second floor, rectangular entrance door, east of the mantlepiece. A cross paneled, mortise and tenon, closet door is placed west of the chimney.

The west half of the second floor of the stone house holds the stair-case and hall on the north and a bedroom on the south. The attic for the stone house was once divided into two rooms, which have been opened up into one large room, lighted by an east and west dormer window and the two, small rectangular south windows.

The floor boards are of random width, tongue-and-groove construction and are being leveled and reset on their opposite sides.

The brick chimney has been exposed and is being repointed and repaired. All the plaster in the room has been removed and plans have been initiated to insulate the roof between the roof's supporting members, allowing some of this construction to be revealed.

In conclusion, the interior of the house retains a great deal of its basic integrity and where change has occurred, such as the hall and staircase, plans for restoration to the original have been made and partially executed by Mr. Hager. An examination of the window frames reveals them to be the originals, although missing some mullions, which will be restored. The house is in a state of becoming totally restored and its progress will be followed with interest.

## 8 SIGNIFICANCE

1400-1499 1500-1599 1800-1699 1700-1799 X1800-1899 1900-	ARCHEOLOGY-PREHISTORIC  ARCHEOLOGY-HISTORIC  AGRICULTURE  ARCHITECTURE  ART  COMMERCE  COMMUNICATIONS	COMMUNITY PLANNING CONSERVATION ECONOMICS EDUCATION ENGINEERING EXPLORATION/SETTLEMENT INDUSTRY INVENTION	LANDSCAPE ARCHITECTURE LAW LITERATURE MILITARY MUSIC PHILOSOPHY POLITICS/GOVERNMENT	RELIGIONSCIENCESCULPTURESOCIAL/HUMANITARIANTHEATERTRANSPORTATIONOTHER (SPECIFY)
SPECIFIC DAT	es circa 1860	BUILDER/ARCH	HITECT	

STATEMENT OF SIGNIFICANCE

Mount Misery is significant to Howard County and the State of Maryland architecturally as a fine example of Howard County vernacular stone architecture and historically as a piece of property once owned by George Ellicott and noted on an 1840 plat, and believed by Mr. and Mrs. Ash, previous owners, to have been constructed in 1843.

It is in its architecture that the building excells, featuring squarely cut granite blocks on its east facade with vertically aligned, proportionally scaled fenestration.

Mount Misery features typical Howard County building techniques, constructed into a slope of land so that its foundation floor is a first floor on the east and a cellar on the west. This is found along the north side of Main Street in Ellicott City and along Old Columbia Pike.

This building is located within the Ellicott City National Register District, as well as the local historic district of Ellicott City and will be impacted by the Cat Rock Storm Drainage and Sewer Project of the Howard County Department of Public Works.

# 9 MAJOR BIBLIOGRAPHICAL REFERENCES

Howard County Land Records
Interview with Mr. Guy Hager at his residence, Saturday, April 19, 1980.
Private papers of Mr. Guy Hager.
Holland, Celia, Ellicott City, Maryland, Milltown, U.S.A., Tuxedo, 1970.

CONTINUE ON SEPARATE SHEET IF NE	CCESSARY
10 GEOGRAPHICAL DATA  ACREAGE OF NOMINATED PROPERTY Lot #14 an	d 2 lots
Please see Attachment 1, Tax	: Map 25A
VERBAL BOUNDARY DESCRIPTION	
Please see Howard County Lan	d Records, Liber <u>246</u> Folio <u>87</u>
LIST ALL STATES AND COUNTIES FOR PROPER	TIES OVERLAPPING STATE OR COUNTY BOUNDARIES
STATE Maryland	COUNTY Howard
STATE	COUNTY
FORM PREPARED BY  NAME / TITLE  Cleora Barnes Thompson, Archivist	
ORGANIZATION	DATE
Office of Planning & Zoning-Compret	nersive Planning Section
3450 Court House Drive	TELEPHONE
Ellicott City	STATE

The Maryland Historic Sites Inventory was officially created by an Act of the Maryland Legislature, to be found in the Annotated Code of Maryland, Article 41, Section 181 KA, 1974 Supplement.

The Survey and Inventory are being prepared for information and record purposes only and do not constitute any infringement of individual property rights.

RETURN TO: Maryland Historical Trust
The Shaw House, 21 State Circle
Annapolis, Maryland 21401
(301) 267-1438


Maryland


### TITLE SEARCH


### HO-557 MOUNT MISERY


## prepared by Cleora B. Thompson


DATE	LIBER-FOLIO	GRANTOR	GRANTEE	TRANSACTION
9 Nov. 1979		Charles E. & Marie Ash	Guy W. Hager	Deed Lot #41
10 July 1953	246-87	Wilbur Kinsey	Charles E. & Marie Ash	Deed Lot #41
22 May 1920	110-227	H. Thomas Grimes	Wilbur and Lillie Mae Kinsey	Deed Lot #41
24 Jan. 1920	109-189	James Clark, et al	H. Thomas Grimes	Deed Lot #41 \$1,675.00
1 Feb. 1896	65-182	John L. Clark & Edward L. Talbott, executors	Sarah R. Talbott	All of Lot #46 as found on plat #2 of 1840, except that conveyed in a deed 42-339, Sept. 2, 1880
2 Sept. 1880	42-339	Edward A. Talbott Mary J. Talbott	Laura J. Kirkwood	NOTE: Here we have a division of Lot #46. That section north of the Guy Hager House com- prises this Kirk- wood House.
















HO-557 Name:

Mount Misery

Location: 8469 Hill Street

Ellicott City, Maryland 21043 : Cleora B. Thompson, A.I.C.P. Photographer:

Date of photograph:

Date of photograph: April, 1980 Negatives in possession of the Maryland Historical Trust

East View:

Photographer looking: West Photograph number: 1 of 1