# INDIVIDUAL PROPERTY/DISTRICT MARYLAND HISTORICAL TRUST INTERNAL NR-ELIGIBILITY REVIEW FORM

Property/District Name: Country Corner	Survey Number: HO-700
Tax Parcel#: 212	
Project: Maryland 216/29 Project Planning Study	Agency: MDOT-SHA
Site visit by MHT Staff:noyes Name	Date
Eligibility recommended Eligibility not rec	commended X
Criteria:ABCD Considerations:A	ABCDEFGNone
Justification for decision: (Use continuation sheet if necessity)	essary and attach map)
The house at 10570 Scaggsville Road is not eligible due Criteria A, B, C, or D. Preliminary research has not reverents that have made a significant contribution to the blives of persons significant in our past (Criterion B). A Colonial Revival style, it is neither unusual nor distinguisplay high artistic merit (Criterion C). There is no evimportant in history or prehistory (Criterion D). Thus, to	vealed any association between the dwelling and broad patterns of our history (Criterion A) or the lthough the building provides an example of the ished; it does not represent the work of a master or idence that the property is likely to yield information
Documentation on the property/district is presented in:	Maryland Historical Trust Inventory Form
and Maryland 29/216 Project Planning Report	
Prepared by: <u>Traceries, 5420 Western Ave., Chevy Cha</u>	se, MD 20815 November 1997
Corcer - all much	2/10/98
Reviewer, Office of Preservation Services	Date
NR program concurrence: <u>y</u> yesnonot applica	ble
Bkurte	3/3/199
Reviewer, NR Program	Date

and

## CAPSULE SUMMARY

10570 Scaggsville Road (HO-700)

The store at 10570 Scaggsville Road was erected in 1901 for Joseph D. Harding, a local landowner who purchased 110 acres from Jeremiah Hegeman in 1900. The store displays vernacular elements commonly associated with rural commercial facilities. Although significantly altered by the removal of the two-story front porch, the store retains its original form.

The store consists of a 2-1/2-story wood frame building with a rectangular footprint. The main block of the original building sits on a solid, poured concrete foundation and is clad in stucco on the first story with asbestos shingles above. A single, corbeled-cap brick interior chimney pierces the roofline, while an metal stovepipe enclosure is attached on the north elevation. The building has been enlarged by the construction of the one-story side addition with a parapet roof. This wood frame commercial addition, clad in asbestos shingles, has a single entry opening and triple show window.

After its construction in 1901, the store remained in the hands of Joseph Harding until 1933, when it was sold to Edna M. and Charles M. Ridgely. That same year, Harding subdivided a portion of his 110 acres of land at the northwest corner of Scaggsville Road and Leishear Road into five lots. The store was located on lot 1. The Ridgelys owned the property until 1952, selling it to Homer G. and Thelma A. Spitzer. The current owners, Effrain and Gladys Y. Larenas, and Leon and Elsa G. Lorenas, acquired to property at 10570 Scaggsville Road in 1984. Not longer operating as a commercial store, the building is currently for sale.

MARYLAND HISTORICAL TRUST MD INVENTORY OF HISTORIC PROPERTIES	Inventory No. <u>HO-700</u>
1. Name of Property	
historic name	
2. Location	
street & number 10570 Scaggsville Road not city or town Laurel vicinity state county _Howard County code _27 zip code	<u>Maryland</u> code <u>MD</u>
3. State/Federal Agency Certification	N/A
4. National Park Service Certification	N/A
5. Classification	
Ownership of Property (Check all that apply  X private public-local public-State public-Federal	)
Category of Property (Check only one box)  X building(s)  district  site  structure object	
0       0       sit         0       0       str	uctures ects
Is this property listed in the National Reg Yes Name of Listing No $\underline{X}$	ister?

Maryland Inventory of Historic Properties Country Corner 10570 Scaggsville Road Howard County, Maryland

of the property.)

Inventory No. HO-700 Page 2

========	=======================================	==
6. Function	ı or Use	
========	=======================================	==
Historic Fu	unctions (Enter categories from instructions)	
cat: _	COMMERCE/TRADE Sub: Specialty Store	
_		
_		_
Current Fur	agtions (Enter satesories from instructions)	
	nctions (Enter categories from instructions)	
Cat: _	<u>COMMERCE/TRADE</u> Sub: <u>Specialty Store</u>	
_		_
_		—
========		==
7. Descript	ion	
========		==
Architectur	cal Classification (Enter categories from instructions	<b>=</b> \
		<i>)</i>
_	Vernacular	
_		
_		
Materiale (	(Enter categories from instructions)	
	ation <u>Solid: Poured Concrete</u>	
roof	Gable: Asphalt Shingles	
walls	Wood Frame: Stucco/Asbestos Shingles	
other	New Trainer State of Trainer State of S	
Ocher		

See Continuation Sheet No. 7-1

Narrative Description (Describe the historic and current condition

Maryland Inventory of Historic Properties Country Corner 10570 Scaggsville Road Howard County, Maryland

Inventory No. HO-700 Page 3

8. Statement of Significance		
Applicable Nat	ional Register Criteria (Mark "x" in one or more criteria qualifying the property for National	
A	Property is associated with events that have made a significant contribution to the broad patterns of our history.	
В	Property is associated with the lives of persons significant in our past.	
<u>X</u> C	Property embodies the distinctive characteristics of a type, period, or method of construction or represents the work of a master, or possesses high artistic values, or represents a significant and distinguishable entity whose components lack individual distinction.	
D	Property has yielded, or is likely to yield information important in prehistory or history.	
Criteria Considerations (Mark "X" in all the boxes that apply.)		
A	owned by a religious institution or used for religious purposes.	
В	removed from its original location.	
C	a birthplace or a grave.	
D	a cemetery.	
Е	a reconstructed building, object, or structure.	
F	a commemorative property.	
G	less than 50 years of age or achieved significance within the past 50 years.	

Maryland Inventory of Historic Properties Country Corner 10570 Scaggsville Road

Inventory No. HO-700 Page 4

Howard County, Maryland	rage r
Areas of Significance (Enter categories from instructional Architecture Commerce	======= ns)
Period of Significance 1901-1947	_
Significant Dates 1901	
Significant Person (Complete if Criterion B is marked	above)
Cultural Affiliation <u>Undefined</u>	
Architect/Builder <u>Unknown</u>	
Narrative Statement of Significance (Explain the signithe property.)	ficance of
See Continuation Sheet No. <u>8-1</u>	

Inventory No. HO-700 10570 Scaggsville Road Page 5 Howard County, Maryland 9. Major Bibliographical References (Cite the books, articles, legal records, and other sources used in preparing this form.) Howard County Land Records, Recorder of Deeds, Howard County, Ellicott City, Maryland. 10. Geographical Data \_\_\_\_\_ Acreage of Property <u>27,442 Square Feet</u> Verbal Boundary Description (Describe the boundaries of the property.) The property at 10570 Scaggsville Road is designated as Parcel 212, Grid 12 as indicated on Map 46. Boundary Justification (Explain why the boundaries were selected.) The property at 10570 Scaggsville Road has historically been associated with Parcel 212 since the original construction of the building in 1901. -----11. Form Prepared By name/title <u>Kathryn Ann Gettings, Architectural Historian</u> organization <u>Traceries</u> \_\_\_ date <u>October 27,1997</u> street & number <u>5420 Western Avenue</u> telephone 301/656-5283 city or town <u>Chevy Chase</u> state <u>MD</u> zip code <u>20815</u> 12. Property Owner name Effrain and Gladys Y. Larenas; Leon and Elsa G. Larenas street & number \_7501 Flamewood Dr. \_\_\_\_\_ telephone \_\_\_\_ city or town <u>Clarksville</u> state <u>MD</u> zip code 21029

\_\_\_\_\_\_\_

Maryland Inventory of Historic Properties

Country Corner

MARYLAND INVENTORY OF HISTORIC PROPERTIES CONTINUATION SHEET

Inventory No. HO-700

Section \_\_7\_\_ Page \_\_1\_\_

10570 Scaggsville Rd.
name of property
Howard County, Maryland
county and state

The 1901 store at 10570 Scaggsville Road consists of a 2-1/2-story wood frame building with a rectangular footprint. The main block of the original building sits on a solid, poured concrete foundation and is clad in stucco on the first story with asbestos shingles above. A single, corbeled-cap brick interior chimney pierces the roofline, while an metal stovepipe enclosure is attached on the north elevation. This vernacular building has been enlarged by the construction of the one-story side addition with a parapet roof. This wood frame commercial addition, clad in asbestos shingles, has a single entry opening and triple show window.

The store occupies a corner lot at the northwest corner of Leishear and Scaggsville roads. The property consists of 27,442 square feet of level, grassy land. The building stands approximately fifteen feet from Scaggsville Road with a gravel parking area at the front. A few mature trees grow at the rear and west sides of the building.

#### **EXTERIOR DESCRIPTION:**

The facade, or southwest elevation, of the store at 10570 Scaggsville Road is three-bays wide with a one-story porch extending across the width of the building. The porch has a shed roof supported by square posts. The first story contains a centered double-leaf wood paneled door with square-edged wood trim. This main entrance is flanked by single 6/6 windows on either side, similarly trimmed with square-edged wood molding. The second story has three openings: a central entry with a panel-and-light door flanked by 6/6 windows. Replacement asbestos shingles indicate the facade originally had a two-story, full-width porch, a typical feature of rural commercial establishments. The windows and door on the second story retain their original square-edged wood trim. A single 1/1 window pierces the third story of the south elevation.

The one-story wood frame addition extending off the southwest elevation of the original store building sits on a poured concrete foundation and is fronted by a wood parapet wall used for signage. The addition is sheltered by a standing seam metal shed roof and clad with asbestos shingles. The facade has a single entry opening, filled with a panel-and-light wood door, and a triple show window with both 1/1 and fixed lights. The parapet wall is crowned by a molded wood cornice.

MARYLAND INVENTORY OF HISTORIC PROPERTIES CONTINUATION SHEET

Inventory No. HO-700

Section 7 Page 2

10570 Scaggsville Rd.
name of property
Howard County, Maryland
county and state

The first story of the southeast elevation facing Leishear Road is obscured by the 1-story east addition, thus, only the second story of the original building is visible. It is pierced by four windows openings, unequally spaced, filled with 6/6 windows and adorned by square-edged wood moldings. The southeast elevation of the onestory addition has a triple window in the westernmost bay. This window is similar to the one found on the facade, containing both 1/1 and fixed lights.

The northeast elevation of the original building contains one 1/1 window on the first story and two 6/6 windows on the second story. These windows are trimmed with square-edged wood moldings. The northeast elevation also contains an exterior end metal chimney stack. The northeast elevation of the one-story addition has a row of three two-light awning windows. Mechanical equipment, extending to the exterior end chimney stack on the original main block, pierces the elevation at the eastern corner.

The first story of the northwest elevation has a single entry opening with a replacement door. Elongated openings, paired and single respectively, mark the first story to the west. The paired openings have replacement 1/1 windows, while the single opening has a 6/6 window. The plane of the wall, at the first story only, from the west edge of the entry to the southwest corner is clad with stucco, while the remaining bay has asbestos shingles. The second story holds four window openings, unequally spaced. The opening directly above the entry has a replacement 1/1 sash, while the remaining windows are 6/6. The windows on this elevation have square-edged trim.

#### **OUTBUILDINGS:**

There is one historic outbuilding associated with the store at 10570 Scaggsville Road: a one-story wood frame garage with a gable roof. The garage stands near the north corner of the property and faces southwest onto Scaggsville Road. Dating from the 1920s or 1930s, the building is clad in German siding. The gable roof, covered with standing seam metal, incorporates a wide overhanging eave with exposed rafter ends. The entry opening contains a double-leaf paneled wood door. Two shed additions, one of wood frame and the other of sheet metal, extend from the rear of the garage to the northeast.

MARYLAND INVENTORY OF HISTORIC PROPERTIES CONTINUATION SHEET

Inventory No. HO-700

Section 8 Page 1

10570 Scaggsville Rd.
name of property
Howard County, Maryland
county and state

The store at 10570 Scaggsville Road was erected in 1901 for Joseph D. Harding, a local landowner who purchased 110 acres from Jeremiah Hegeman in 1900. The store displays vernacular elements commonly associated with rural commercial facilities. Although significantly altered by the removal of the two-story front porch, the store retains its original form.

After its construction in 1901, the store remained in the hands of Joseph Harding until 1933, when it was sold to Edna M. and Charles M. Ridgely. That same year, Harding subdivided a portion of his 110 acres of land at the northwest corner of Scaggsville Road and Leishear Road into five lots. The store was located on lot 1. The Ridgelys owned the property until 1952, selling it to Homer G. and Thelma A. Spitzer. The current owners, Effrain and Gladys Y. Larenas, and Leon and Elsa G. Lorenas, acquired to property at 10570 Scaggsville Road in 1984. Not longer operating as a commercial store, the building is currently for sale.

Inventory No. HO-700

10570 Scaggsville Rd. name of property Howard County, Maryland

county and state

HISTORIC CONTEXT:

Geographic Organization: Piedmont

Chronological/Development Period (s):

Industrial/Urban Dominance (1870-1930)

Modern Period (1930-present)

Prehistoric/Historic Period Theme (s):

Architecture, Landscape, and Community

Planning

Economic (Commercial)

RESOURCE TYPE(S)

Category: Building

Historic Environment: Rural

Historic Function (s): COMMERCE/TRADE

Known Design Source: Unknown

Inventory No. HO-700

10570 Scaggsville Rd.
name of property
Howard County, Maryland
county and state

### Chain of Title:


September 3, 1900 Jeremiah Hegeman to Joseph D. Harding Land Records of Howard County Liber JHO 72 Folio 380


September 9, 1933 Joseph D. Harding to Edna M. and Charles M.
Ridgely
Part of previous property
Land Records of Howard County
Liber BMJr.
Folio 210

\_\_\_\_\_\_\_

September 10, 1952 Edna M. Ridgely to Homer G. and Thelma A.
Spitzer
Land Records of Howard County
Liber MWB Folio 259

May 14, 1984 Homer G. and Thelma A. Spitzer to Effrain and Gladys Y. Larenas and Leon and Elsa G. Larenas Land Records of Howard County
Liber CMP 1250 Folio 74







HO-700 Country Corner 10570 Scaggsville Rd. Howard County, MD Traceries September 1997 Manyland SHPO Store, South corner 10f 6




40-700 Country Corner 10570 Scaggsville Rd Howard County, MD Traceries September 1997 Manyland SHPO Store, W Corner 204 6



40-700 Cantry Corner
10570 Scagsmile 120L
Howard County, LID
Tracenes September 1997 Manyland SHPO Store, NW Elevation



40-700 Cantry Corner 10570 Scaggsville Rd. Howard County MD Traceries September 1997 Manyland SHPO Store, E corner 4046



HO-700 Country Corner 10570 Scaggsville Rd. Howard County, MD Traceries September 1997 Manyland SHPO Store, SE Elevation 5 of 6



HO-700 Country Corner 10570 Scaggerille Rd. Howard County, MD Tracenes September 1997 Manyland SHPO Garage, SE Elevation