INDIVIDUAL PROPERTY/DISTRICT MARYLAND HISTORICAL TRUST INTERNAL NR-ELIGIBILITY REVIEW FORM

Property/District Name: 10600 Shaker Drive Survey Number: HO-723	
Tax Parcel#: 54	
Project: Maryland 216/29 Project Planning Study Agency: MDOT-SHA	
Site visit by MHT Staff:noyes Name Date	
Eligibility recommended Eligibility not recommended X	
Criteria:ABCD Considerations:ABCDEF _X_GNone	
Justification for decision: (Use continuation sheet if necessary and attach map)	
The house at 10600 Shaker Drive is not eligible due to the fact that it does not meet National Register Criteria A, B, C, or D. Preliminary research has not revealed any association between the dwelling and events that have made a significant contribution to the broad patterns of our history (Criterion A) or the lives of persons significant in our past (Criterion B). Although the building provides an example of the Craftsman-Bungalow style, it is neither unusual nor distinguished; it does not represent the work of a maste or display high artistic merit (Criterion C). There is no evidence that the property is likely to yield information important in history or prehistory (Criterion D). In addition, the dwelling is less than fifty year of age (Criterion G of Criteria Considerations). Thus, the property is not National Register-eligible.	
Documentation on the property/district is presented in: Maryland Historical Trust Inventory Form	
and Maryland 29/216 Project Planning Report	
Prepared by: Traceries, 5420 Western Ave., Chevy Chase, MD 20815 November 1997 Reviewer, Office of Preservation Services Date	
NR program concurrence: Xyesnonot applicable	
Reviewer, NR Program 3 \ 31 \ 97 Date	

CAPSULE SUMMARY

10600 Shaker Drive (HO-723)

The 1949 Craftsman-style Bungalow is a one-and-one-half-story, three-bay, front gable roof residence with a one story, wood frame, side gable porch wrapping around the majority of the facade and part of the southwest elevation. The house appears as it did when it was originally constructed. The wood frame dwelling, which sits on a solid foundation, is clad in uncoursed ashlar. An interior stone chimney rises above the asphalt shingled roof.

The Craftsman-style Bungalow was the style of choice for dwellings erected in rural communities across America in the 1920s and 1930s and even into the 1940s. Due to the agrarian nature of the Scaggsville area, the Bungalow remained popular long after it had fallen out of favor in more urban areas. The house at 10600 Shaker Drive, erected in 1949, reflects this trend. The simplified Craftsman-style Bungalow was popular because it provided homeowners with an affordable residence that was both easy to construct and to maintain.

MARYLAND HISTORICAL TRUST MD INVENTORY OF HISTORIC PROPERTIES	Inventory No. <u>HO-723</u>
1. Name of Property	
historic name	
2. Location	
street & number 10600 Shaker Drive not city or town Columbia vicinity state county Howard code 027 zip code	for publication Maryland code _MD
3. State/Federal Agency Certification	N/A
4. National Park Service Certification	N/A
5. Classification	
Ownership of Property (Check all that apply X private public-local public-State public-Federal)
Category of Property (Check only one box) X building(s) district site structure object	
$\begin{array}{c c} \underline{0} & \underline{0} & \text{site} \\ \underline{0} & \underline{1} & \text{str} \end{array}$	uctures ects
Is this property listed in the National Reg Yes Name of Listing No \underline{X}	ister?

Maryland Inventory of Historic Properties 10600 Shaker Drive Howard County, Maryland

of the property.)

Inventory No. HO-723 Page 2

6. Function or Use
Historic Functions (Enter categories from instructions) Cat: DOMESTIC Sub: Single Dwelling
Current Functions (Enter categories from instructions) Cat: DOMESTIC Sub: Single Dwelling
7. Description ===================================
Materials (Enter categories from instructions) foundation Solid: Stone Cladding roof Front Gable: Asphalt Shingle walls Wood Frame: Stone, Uncoursed Ashlar other
Narrative Description (Describe the historic and current condition

See Continuation Sheet No. 7-1

8. Statement of Significance		
Applicable Nat	ional Register Criteria (Mark "x" in one or more criteria qualifying the property for National	
A	Property is associated with events that have made a significant contribution to the broad patterns of our history.	
В	Property is associated with the lives of persons significant in our past.	
<u>X</u> C	Property embodies the distinctive characteristics of a type, period, or method of construction or represents the work of a master, or possesses high artistic values, or represents a significant and distinguishable entity whose components lack individual distinction.	
D	Property has yielded, or is likely to yield information important in prehistory or history.	
Criteria Considerations (Mark "X" in all the boxes that apply.)		
A	owned by a religious institution or used for religious purposes.	
В	removed from its original location.	
C	a birthplace or a grave.	
D	a cemetery.	
E	a reconstructed building, object, or structure.	
F	a commemorative property.	
<u>X</u> G	less than 50 years of age or achieved significance within the past 50 years.	

Maryland Inventory of Historic Properties 10600 Shaker Drive Howard County, Maryland

Inventory No. HO-723 Page 4

Areas of Significance (Enter categories from instructions) Architecture
Period of Significance 1949-present
Significant Dates 1949
Significant Person (Complete if Criterion B is marked above)
Cultural Affiliation <u>Undefined</u>
Architect/Builder <u>Unknown</u>
Narrative Statement of Significance (Explain the significance of the property.)
See Continuation Sheet No. <u>8-1</u>

Maryland Inventory of Historic Properties 10600 Shaker Drive Howard County, Maryland

Inventory No. HO-723 Page 5

MARYLAND INVENTORY OF HISTORIC PROPERTIES CONTINUATION SHEET

Inventory No. HO-723

Section __7_ Page _1_

10600 Shaker Drive
name of property
Howard County, Maryland
county and state

The 1949 Craftsman-style Bungalow is a one-and-one-half-story, three-bay, front gable roof residence with a one story, wood frame, side gable porch wrapping around the majority of the facade and part of the southwest elevation. The wood frame dwelling, which sits on a solid foundation, is clad in uncoursed ashlar. An interior stone chimney rises above the asphalt shingled roof.

The house at 10600 Shaker Drive is set on a rise above Old Columbia Road. A stone retaining wall, dated 1950, sits to the southeast of the house along the driveway. A row of evergreens shields the dwelling from Shaker Drive and Route 29 to the northwest, and matures trees line the property on the northeast. Large shrubs surround the foundation of the northwest facade.

EXTERIOR DESCRIPTION:

Two of the three bays of the northwest elevation, the facade, are covered by the one-story, gable roof porch with Craftsman-style supports. The main entrance is marked by a single-leaf, paneled door with lights. The first story is pierced by two sets of windows. Each set is formed by a fixed single-light flanked by two 2/2 metal sash windows. Each window opening at the first story is set on a stone sill. The upper half story contains a pair of 1/1 metal sash windows with square edged sills.

The foundation wall of the northeast elevation is pierced by three window openings with stone sills. Two of the openings are filled with a two-light metal awning window while the third holds one three-light metal awning window. The first story is marked by two pairs of 2/2 metal sash windows with stone sills and by a group of three smaller two-light metal casement windows. The roof is pierced by two front gable dormers clad in vinyl siding. Each dormer holds a pair of 2/2 metal sash windows.

The southeast elevation is pierced at the foundation by two three-light metal awning windows with stone sills. The first story is marked by three 2/2 metal sash windows with stone sills and a by single leaf, wood paneled door with lights and a stone sill. Within the upper half-story is a 2/2 metal sash window with a stone sill.

The basement level of the southern end of the southwest elevation is on grade and holds an overhead rolling metal garage door. To the north of this door, the foundation wall is also pierced by one three-light metal awning with a stone sill. The northern half of

MARYLAND INVENTORY OF HISTORIC PROPERTIES CONTINUATION SHEET

Inventory No. <u>HO-723</u>

Section _ 7_ Page _2_

10600 Shaker Drive
name of property
Howard County, Maryland
county and state

the first story is covered by the one-story, wood frame, front gable, portion of the L-shaped porch. Here the first story is pierced with two two-light metal casement windows and by a group of metal windows -- a six-light metal window flanked by two three-light casements and crowned by a fixed four-light transom above. Also at the southern end of the first story is a second group of windows -- a single fixed light that is flanked by three-light metal casement windows. All the windows at the foundation and first story rest on stone sills. The upper half story at this elevation is marked by a pair of 2/2 metal sash windows set within a gable roof dormer.

OUTBUILDINGS:

A front gable garage with a concrete pad sits to the south of the main house. Dating to the 1940s, the garage is clad in vinyl siding, has one 4/4 window, and a double-leaf vertical board door.

An in-ground concrete swimming pool sits to the southeast of the main house behind the garage.

MARYLAND INVENTORY OF HISTORIC PROPERTIES CONTINUATION SHEET

Inventory No. <u>HO-723</u>

Section 8 Page 1

10600 Shaker Drive
name of property
Howard County, Maryland
county and state

The Craftsman-style Bungalow was the style of choice for dwellings erected in rural communities across America in the 1920s and 1930s and even into the 1940s. Due to the agrarian nature of the Scaggsville area, the Bungalow remained popular long after it had fallen out of favor in more urban areas. The house at 10600 Shaker Drive, which appears much as it did when it was erected in 1949, reflects this trend. The simplified Craftsman-style Bungalow was popular because it provided homeowners with an affordable residence that was both easy to construct and to maintain.

According to the current owner, Louis Brown, the dwelling was built in 1949 by Thomas Hardy Jarvis. Jarvis acquired the land in July of 1942 from Katherine W. Cooke.

Inventory No. HO-723

10600 Shaker Drive name of property Howard County, Maryland county and state

HISTORIC CONTEXT:

Geographic Organization: Piedmont

Chronological/Development Period (s):

Modern Period (1930-present)

Prehistoric/Historic Period Theme (s):

Architecture, Landscape, and Community

Planning

RESOURCE TYPE(S)

Category: Building

Historic Environment: Rural

Historic Function (s): DOMESTIC/ Single Dwelling

Known Design Source: Unknown

Inventory No. HO-723

10600 Shaker Drive name of property Howard County, Maryland

county and state

Chain of Title:

March 17, 1914: Mary

Mary Gambrill Jones to Francis Cooke Francis Cooke died ca. October 24, 1937

Deeded property to his wife, Katherine M.

Cooke

Will Records of Baltimore City

Liber JHB 190 Folio 396

Land Records of Howard County

Liber WWLC 96 Folio 547

July 10, 1942:

Katherine W. Cooke to Thomas Hardy Jarvis

309 acres

Land Records of Howard County Liber E.M. Jr. 175 Folio 223

March 27, 1947:

Thomas H. and Mettie E. (wife) Jarvis to Louis

M. Brown .541 acres

Part of tract conveyed by Katherine Cooke to


Thomas H. Jarvis

Land Records of Howard County


Liber 197 Folio 126

10600 Shaker Drive Columba, Howard County, MD





Route 29







HO-723 10600 Shaker Dr Howard County, MP Traceries October 1997 Maryland SHPO House, NW Elevation 1 of 6




HO-723 10600 Snaker Dr. Howard County, MD Traceries October 1997 Maryland SHPO House, NE Elevation 2 d 6




HO-723 10600 Snaker Dr Howard County, MD Traceries October 1997 Maryland SHPO House, SE Elevation 30+6



HO-723 10000 Shaker Dr Howard County, MD Traceries October 1997 Maryland SHPO House, SW Elevation 4 & 6



HO-723 10600 Shaker Dr Howard County, MD Traceries October 1997 Maryland SHPO Garage, N Corner 546



HO-723 10600 Staker Dr Howard County, MD Traceries October 1997 Maryland SHPO Inground pool, Looking SE 6 of 6