

Howard County Pipe Break Field Data

Location and Contact information			
Date	2/19/11	Time	15:00
Crew Leader name	C. Carroll	Crew Leader phone #	44900
Address	5030 Montgomery Road Fellsmere City, Md 21043		
ADC page	4936	ADC Grid	D3
Base Map #	2844	Contract #	64

Soil Type

Type	Check box	Type	Check box
Clay	<input checked="" type="checkbox"/>	Clay/sand	<input type="checkbox"/>
Sand	<input checked="" type="checkbox"/>	Blue/gray clay	<input type="checkbox"/>
Silt	<input checked="" type="checkbox"/>		<input type="checkbox"/>

Pipe Type

Type	Check box	Type	Check box
Cast iron	<input checked="" type="checkbox"/>	PCCP/Concrete	<input type="checkbox"/>
Ductile iron	<input type="checkbox"/>	Plastic PVC	<input type="checkbox"/>
Steel	<input type="checkbox"/>	Plastic polyethylene	<input type="checkbox"/>
AC/Transite	<input type="checkbox"/>	polyethylene	<input checked="" type="checkbox"/>

Type of Break

Type	Check box	Type	Check box
Circular	<input type="checkbox"/>	Damage by others	<input type="checkbox"/>
Split	<input type="checkbox"/>	Pipe Joint leak	<input type="checkbox"/>
Fitting leak	<input type="checkbox"/>	Valve problem	<input type="checkbox"/>
		Failed WHC	<input checked="" type="checkbox"/>

Size of Pipe

Size in inches	3/4
----------------	-----

replaced sheared poly B WHC with 3/4-inch copper

M. Tucker