

Howard County Pipe Break Field Data

| Location and Contact information | | | |
|----------------------------------|-------------------|---------------------|--------------|
| Date | 12-7-12 | Time | |
| Crew Leader name | Duane Bozzell | Crew Leader phone # | 410-313-4900 |
| Address | 6253 CHICKET PASS | | |
| ADC page | 4934 | ADC Grid | J8 |
| Base Map # | 2539 | Contract # | 488 |

Soil Type

| Type | Check box | Type | Check box |
|------|-------------------------------------|----------------|-----------|
| Clay | | Clay/sand | |
| Sand | | Blue/gray clay | |
| Silt | <input checked="" type="checkbox"/> | | |

Pipe Type

| Type | Check box | Type | Check box |
|--------------|-------------------------------------|----------------------|-----------|
| Cast iron | <input checked="" type="checkbox"/> | PCCP/Concrete | |
| Ductile iron | | Plastic PVC | |
| Steel | | Plastic polyethylene | |
| AC/Transite | | | |

Type of Break

| Type | Check box | Type | Check box |
|--------------|-------------------------------------|------------------|-----------|
| Circular | <input checked="" type="checkbox"/> | Damage by others | |
| Split | | Pipe Joint leak | |
| Fitting leak | | Valve problem | |

Size of Pipe

| | |
|----------------|----|
| Size in inches | 6" |
|----------------|----|