

## Howard County Pipe Break Field Data

	Location and Contact information		
Date <i>11.25.11</i>	<i>6549 Carlisle Dr.</i>	Time <i>4:30 PM</i>	
Crew Leader name	<i>Tom Peckett</i>	Crew Leader phone #	
Address			
ADC page	<i>4935-</i>	ADC Grid <i>D-10</i>	
Base Map #	<i>GRID-36-2440</i>	Contract # <i>886</i>	

### Soil Type

Type	Check box	Type	Check box
Clay		Clay/sand	
Sand		Blue/gray clay	
Silt	<input checked="" type="checkbox"/>		

### Pipe Type

Type	Check box	Type	Check box
Cast iron	<input checked="" type="checkbox"/>	PCCP/Concrete	
Ductile iron		Plastic PVC	
Steel		Plastic polyethylene	
AC/Transite			

### Type of Break

Type	Check box	Type	Check box
Circular	<input checked="" type="checkbox"/>	Damage by others	
Split		Pipe Joint leak	
Fitting leak		Valve problem	

### Size of Pipe

Size in inches	<i>4"</i>
----------------	-----------