

# HOWARD COUNTY: PIPE BREAKS - FIELD DATA

DAY: 2. 23. 09  
 TIME: \_\_\_\_\_  
 TIME OF BREAK: 8:45 AM  
 ENGINEER: PAII Mitchell

**LOCATION:**

GPS LOCATION: 6602 DEVLon PI  
 \_\_\_\_\_  
 \_\_\_\_\_  
 GPS: \_\_\_\_\_

**PHOTO BEFORE REPAIRS:**

Number of Pictures: 950

**SOIL CHEMISTRIES:**

REDOX		SOIL BOX RESISTIVITES		pH	
(mV)		(Ohm-cm)		(mV)	
(mV)		(Ohm-cm)		(mV)	
Top of Pipe (12)		Top of Pipe (12)		Top of Pipe (12)	
Side of Pipe (3 / 9)		Side of Pipe (3 / 9)		Side of Pipe (3 / 9)	
Bottom of Pipe (6)		Bottom of Pipe (6)		Bottom of Pipe (6)	
				Actual Soil pH	

Soil Type:  Clay  Sand  Silt  Clay/sand  BGC\*  Other

**DETAILS:**

Pipe Type:  Cast Iron  Ductile Iron  Steel  PCCP  Plastic

Pipe Size: \_\_\_\_\_

Repair Method:  Clamp  Weld  Cut  Other


**DETAILS:**

Form of Break:  Circular  Longitudinal  Other

**DETAILS:**

**PHOTO AFTER REPAIRS:**

Number of Pictures: \_\_\_\_\_



\* BGC = blue/gray clay