

Howard County Pipe Break Field Data

	Location and Contact information		
Date	8-3-11	Time	
Crew Leader name	Bozzell	Crew Leader phone #	410-313-4900
Address	6734 Montgomery Rd		
ADC page	4937	ADC Grid	A-7
Base Map #	26-46	Contract #	316

Soil Type

Type	Check box	Type	Check box
Clay	<input checked="" type="checkbox"/>	Clay/sand	<input type="checkbox"/>
Sand	<input type="checkbox"/>	Blue/gray clay	<input type="checkbox"/>
Silt	<input type="checkbox"/>		<input type="checkbox"/>

Pipe Type

Type	Check box	Type	Check box
Cast iron	<input checked="" type="checkbox"/>	PCCP/Concrete	<input type="checkbox"/>
Ductile iron	<input type="checkbox"/>	Plastic PVC	<input type="checkbox"/>
Steel	<input type="checkbox"/>	Plastic polyethylene	<input type="checkbox"/>
AC/Transite	<input type="checkbox"/>		<input type="checkbox"/>

Type of Break

Type	Check box	Type	Check box
Circular	<input type="checkbox"/>	Damage by others	<input type="checkbox"/>
Split	<input checked="" type="checkbox"/>	Pipe Joint leak	<input type="checkbox"/>
Fitting leak	<input type="checkbox"/>	Valve problem	<input type="checkbox"/>

Size of Pipe

Size in inches	12
----------------	----