

## Howard County Pipe Break Field Data

|                  |                                  |                     |          |
|------------------|----------------------------------|---------------------|----------|
|                  | Location and Contact information |                     |          |
| Date             | 1-2-12                           | Time                | 10:00 AM |
| Crew Leader name | Tom Puckett                      | Crew Leader phone # |          |
| Address          | 6945 Linden Ave.                 |                     |          |
| ADC page         | 5052                             | ADC Grid            | K2       |
| Base Map #       | 2346                             | Contract #          | 24       |

### Soil Type

| Type | Check box                           | Type           | Check box |
|------|-------------------------------------|----------------|-----------|
| Clay |                                     | Clay/sand      |           |
| Sand |                                     | Blue/gray clay |           |
| Silt | <input checked="" type="checkbox"/> |                |           |

### Pipe Type

| Type         | Check box                           | Type                 | Check box |
|--------------|-------------------------------------|----------------------|-----------|
| Cast iron    | <input checked="" type="checkbox"/> | PCCP/Concrete        |           |
| Ductile iron |                                     | Plastic PVC          |           |
| Steel        |                                     | Plastic polyethylene |           |
| AC/Transite  |                                     |                      |           |

### Type of Break

| Type         | Check box                           | Type             | Check box |
|--------------|-------------------------------------|------------------|-----------|
| Circular     |                                     | Damage by others |           |
| Split        | <input checked="" type="checkbox"/> | Pipe Joint leak  |           |
| Fitting leak |                                     | Valve problem    |           |

### Size of Pipe

|                |    |
|----------------|----|
| Size in inches | 6" |
|----------------|----|

Used Long Range Clamp - 0893