## Howard County Pipe Break Field Data

	Location and Contact information			
Date	11/14/2012		Time	7:00 am
Crew Leader name	Leo Dickey		Crew Leader phone	# 410-446-6317
Address	9020 Overhill drive Ellicott city m Md 21043			
ADC page	4815	ADC Gri	d j-	-7
Base Map #	3142	Contrac	t# 1	.0-w

Soil Type

Туре	Check box	Туре	Check box
Clay		Clay/sand	×
Sand		Blue/gray clay	
Silt			

Pipe Type

Туре	Check box	Туре	Check box
Cast iron	×	PCCP/Concrete	
Ductile iron		Plastic PVC	
Steel		Plastic polyethylene	
AC/Transite			

Type of Break

Туре	Check box	Туре	Check box
Circular	×	Damage by others	
Split		Pipe Joint leak	
Pitting		Valve problem	
Fitting leak			

Size of Pipe

Size of Fipe		
Size in inches	6"	