

Howard County Pipe Break Field Data

Location and Contact information			
Date	12/3/2012	Time	1:00 pm
Crew Leader name	Leo Dickey	Crew Leader phone #	410-446-6317
Address	9939 Naylor avenue scaggsville md 20723		
ADC page	5169	ADC Grid	C2
Base Map #	1741	Contract #	1-w

Soil Type

Type	Check box	Type	Check box
Clay		Clay/sand	
Sand	x	Blue/gray clay	
Silt	x		

Pipe Type

Type	Check box	Type	Check box
Cast iron	x	PCCP/Concrete	
Ductile iron		Plastic PVC	
Steel		Plastic polyethylene	
AC/Transite			

Type of Break

Type	Check box	Type	Check box
Circular	x	Damage by others	
Split		Pipe Joint leak	
Pitting		Valve problem	
Fitting leak		Clamp repair	

Size of Pipe

Size in inches	6"
----------------	----