

Howard County Pipe Break Field Data

| Location and Contact information | | | |
|----------------------------------|-------------------------------|---------------------|--------------|
| Date | 10-13-12 | Time | 7:00 AM |
| Crew Leader name | Chuck GARRETT | Crew Leader phone # | 410 313-4906 |
| Address | Long View Dr + Hickorymede Dr | | |
| ADC page | 4815 | ADC Grid | E4 |
| Base Map # | 3341 | Contract # | 565 ACP |

Soil Type

| Type | Check box | Type | Check box |
|------|-------------------------------------|----------------|-----------|
| Clay | | Clay/sand | |
| Sand | | Blue/gray clay | |
| Silt | <input checked="" type="checkbox"/> | | |

Pipe Type

| Type | Check box | Type | Check box |
|--------------|-------------------------------------|----------------------|-----------|
| Cast iron | | PCCP/Concrete | |
| Ductile iron | | Plastic PVC | |
| Steel | | Plastic polyethylene | |
| AC/Transite | <input checked="" type="checkbox"/> | | |

Type of Break

| Type | Check box | Type | Check box |
|--------------|-----------|------------------|-----------|
| Circular | | Damage by others | |
| Split | | Pipe Joint leak | |
| Fitting leak | | Valve problem | |

Clamp leak

Size of Pipe

| | |
|----------------|----|
| Size in inches | 8" |
|----------------|----|