

Date: 6/08/94


Time: 10:20A - 1:10P

Effective Groundbed Width (ft): 200

Stray Current Shifts (mV): DC 18mV;

Comments: Near MH 8474 (Sta. 85+21)

Figure 16. Stray Current Survey (AM) for Site 2



Date: 6/08/94

Time: 1:20P - 4:05P

Effective Groundbed Width (ft): 200

Stray Current Shifts (mV): DC 11mV;

Comments: Stray current reversed itself, possibly taking new path.

Figure 17. Stray Current Survey (PM) for Site 2



Figure 3. Location of Site 1



Figure 4. Location of Site 2