

HOWARD COUNTY: PIPE BREAKS - FIELD DATA

DAY: 1-30-04
 TIME: 9:00
 TIME OF BREAK: 1-29-04
 ENGINEER: _____

LOCATION:

GPS LOCATION: 5960 Rosiawte Run

GPS: 319-w

PHOTO BEFORE REPAIRS:

Number of Pictures: _____

SOIL CHEMISTRIES:

REDOX		SOIL BOX RESISTIVITIES		pH	
(mV)		(Ohm-cm)		(mV)	
(mV)		(Ohm-cm)		(mV)	
Top of Pipe (12)		Top of Pipe (12)		Top of Pipe (12)	
Side of Pipe (3 / 9)		Side of Pipe (3 / 9)		Side of Pipe (3 / 9)	
Bottom of Pipe (6)		Bottom of Pipe (6)		Bottom of Pipe (6)	
				Actual Soil pH	

Soil Type: ___ Clay ___ Sand ___ Silt Clay/sand ___ BGC* ___ Other

DETAILS:

Pipe Type: Cast Iron ___ Ductile Iron ___ Steel ___ PCCP ___ Plastic

Pipe Size: 3"

Repair Method: Clamp ___ Weld ___ Cut ___ Other


DETAILS:

3" Pipe has a lot of pits in it. Second Break within a week and 4' from Break last week
 Form of Break: Circular ___ Longitudinal ___ Other
DETAILS: Soil Sample collected?

PHOTO AFTER REPAIRS:

Number of Pictures: _____

SKETCH OF SITE



TESTING VIEW

