



Figure 45 - Results of Stray Current Test #4 on Marriottsville Rd

Both graphs display readings that are predominantly greater than zero, indicating that there is an underlying steady state voltage gradient present in the area. The overall pattern of the data in the plot for the north / south electrode array (parallel to the gas pipeline) carries the typical signature of stray current gradients associated with operation of DC power.