## **Dower Drive and East Leisure Court**

Stray current tests were conducted near the intersection of Dower Drive and East Leisure Court. A map and photograph of the location are shown below in Figure 53 and Figure 54, respectively. Measured stray currents indicate a maximum peak-to-peak potential shift of 0.67 volts on the north-south axis.




Figure 53 – Stray current test location near Dower Drive and East Leisure Court



Figure 54 – Measuring stray currents near Dower Drive and East Leisure Court

