



	<u>CuCuSO<sub>4</sub> to CuCuSO<sub>4</sub></u>	<u>Pipe to CuCuSO<sub>4</sub></u>
<b>Approximate Station #:</b>	(02+25)	(02+25)
<b>Date:</b>	4/1/2005	4/1/2005
<b>Time:</b>	13:34:02 AM	13:34:02 AM
<b>Maximum (V):</b>	0.87	0.21
<b>Minimum (V):</b>	-0.26	-1.98
<b>DC Potential Shifts (V):</b>	1.13	2.19
<b>Location:</b>	End of Cedar Avenue	
<b>GPS Location:</b>	N 39° 10.323', W 76° 47.596'	

Figure 217 - Stray Current Test Results for site 1, near Test Station 1



**Figure 218 – Stray Current Test Location - site 1**