

Date: 6/27/94



Time: 9:35A - 12:10P

Effective Groundbed Width (ft): 200

Stray Current Shifts (mV): DC 91 mV;

Comments: Site located at intersection of Mayfield Rd. and Rt. 108.

Figure 42. Stray Current Survey (AM) for Site 15



Date: 6/27/94

Time: 12:20P - 3:40P

Effective Groundbed Width (ft): 200

Stray Current Shifts (mV): DC 50 mV;

Comments:

Figure 43. Stray Current Survey (PM) for Site 15



Figure 13. Location of Site 14



Figure 14. Location of Site 15