



	<u>CuCuSO<sub>4</sub> to CuCuSO<sub>4</sub></u>	<u>Pipe to CuCuSO<sub>4</sub></u>
<b>Approximate Station #:</b>	(11+26)	(11+26)
<b>Date:</b>	3/24/2005	3/24/2005
<b>Time:</b>	10:54:07	10:54:07
<b>Maximum (V):</b>	0.15	-0.96
<b>Minimum (V):</b>	-0.23	-1.63
<b>DC Potential Shifts (V):</b>	0.38	0.67
<b>Location:</b>	South end Test Station	
<b>GPS Location:</b>	N 39° 12.439', W 76° 56.520'	

Figure 125 Stray Current Test Results for section 3231



**Figure 126 - Stray Current Test Location for section 3231**