

## Howard County Pipe Break Field Data

Location and Contact information			
Date	11/16/12	Time	9:00 pm
Crew Leader name	Dave Bezell	Crew Leader phone #	410-313-4910
Address			
ADC page	5053	ADC Grid	45
Base Map #	2142	Contract #	178W

### Soil Type

Type	Check box	Type	Check box
Clay	<input checked="" type="checkbox"/>	Clay/sand	<input type="checkbox"/>
Sand	<input type="checkbox"/>	Blue/gray clay	<input type="checkbox"/>
Silt	<input type="checkbox"/>		<input type="checkbox"/>

### Pipe Type

Type	Check box	Type	Check box
Cast iron	<input checked="" type="checkbox"/>	PCCP/Concrete	<input type="checkbox"/>
Ductile iron	<input type="checkbox"/>	Plastic PVC	<input type="checkbox"/>
Steel	<input type="checkbox"/>	Plastic polyethylene	<input type="checkbox"/>
AC/Transite	<input type="checkbox"/>		<input type="checkbox"/>

### Type of Break

Type	Check box	Type	Check box
Circular	<input checked="" type="checkbox"/>	Damage by others	<input type="checkbox"/>
Split	<input type="checkbox"/>	Pipe Joint leak	<input type="checkbox"/>
Fitting leak	<input type="checkbox"/>	Valve problem	<input type="checkbox"/>

### Size of Pipe

Size in inches	12
----------------	----

repaired with full circle clamp