

## Howard County Traffic Signal Inspection Summary Report:

**Signal Number:** 002

**Location:** Broken Land Parkway at Cradlerock Way - South

**Inspection Date:** April 11, 2018

**Inspection Overall Score:** 36

### Significant Findings:

Poles and paint coating in overall good condition. West Median base plate was buried and had to be dug out. Surface rust beginning to form on the tightening nuts for this structure.



### Maintenance Issues:

N/A