

Howard County Traffic Signal Inspection Summary Report:

Signal Number: 008
Location: Little Patuxent Parkway at Cedar La.
Inspection Date: February 27, 2018

Inspection Overall Score: 36

Significant Findings:

Poles and paint coating are in overall fair condition. Both structures have small areas of paint coating failure, with surface rust beginning to form. Recommend cleaning, prime, and re-paint.



Maintenance Issues:

N/A