

Howard County Traffic Signal Inspection Summary Report:

Signal Number: 014
Location: Old Columbia Rd. at Eden Brook/Shaker Dr.
Inspection Date: May 1, 2018

Inspection Overall Score: 26

Significant Findings:

Poles and paint coating in overall good condition. Surface rust beginning to form around the base plate area, anchor bolts, and leveling and tightening nuts.



Maintenance Issues:

SW Corner – loose tightening nuts.
NW Corner – overgrowth should be trimmed from around this structure.

