

Howard County Traffic Signal Inspection Summary Report:

Signal Number: 019
Location: Little Patuxent Parkway at Harpers Farm Rd.
Inspection Date: February 27, 2018

Inspection Overall Score: 21

Significant Findings:

Poles are in overall good condition. Paint coating is in good condition with a few small spots of coating failure.



Maintenance Issues:

West Median – mast-arm bolts appear to be too short and not properly threaded.

