

Howard County Traffic Signal Inspection Summary Report:

Signal Number: 023

Location: Little Patuxent Parkway at South Entrance Rd.?

Inspection Date: April 11, 2018

Inspection Overall Score: 41

Significant Findings:

Poles in overall fair condition. Paint coating is in good condition. Both structures have some moderate rusting around the base plate area and tightening nuts. Recommend media blast, prime, and re-paint.



Maintenance Issues:

N/A