

Howard County Traffic Signal Inspection Summary Report:

Signal Number: 025
Location: Twin Rivers Rd. at Lynx La.
Inspection Date: May 1, 2018

Inspection Overall Score: 49

Significant Findings:

Paint coating is in fair condition with rust beginning in some areas. NW structure has moderate rusting around the base plate area, anchor bolts, and leveling nuts.



Maintenance Issues:

Crosswalks in fair condition.