

## Howard County Traffic Signal Inspection Summary Report:

**Signal Number:** 028  
**Location:** Snowden River Parkway at Oakland Mills Rd.  
**Inspection Date:** May 2, 2018

**Inspection Overall Score:** 64

### Significant Findings:

Combination of one mast-arm and three spans. Older span wire poles have cast iron base plates. Poles are in fair condition with some coating failure, and light rusting around the base plate and tightening nuts. Pole on NE corner has vehicle impact damage. Newer mast-arm pole has significant coating failure.



### Maintenance Issues:

NE and NW Corners – loose tightening nuts.