Howard County Traffic Signal Inspection Summary Report:

Signal Number: 030

Location: Frederick Rd. at St. Johns La.

Inspection Date: June 6, 2018

Inspection Overall Score: 26

Significant Findings:

Poles and paint coating in overall good condition. Rust forming around the base plate area, anchor bolts, and tightening nuts. Multiple instances of utility lines laying on the mast-arms. Recommend cleaning, prime, and re-paint.



Maintenance Issues:

SE Corner – loose tightening nuts. Area around the NW corner pole needs to be re-graded to prevent the base plate from becoming buried.



