

Howard County Traffic Signal Inspection Summary Report:

Signal Number: 033

Location: Little Patuxent Parkway at Vantage Point/Running Brook

Inspection Date: February 27, 2018

Inspection Overall Score: 51

Significant Findings:

Poles in overall fair condition, with moderate rusting around the base plate area, anchor bolts, and tightening nuts. Both base plates were buried and had to be dug out.



Maintenance Issues:

Crosswalks and stop lines in fair condition.