

Howard County Traffic Signal Inspection Summary Report:

Signal Number: 034
Location: Cedar La. at Freetown Rd.?
Inspection Date: April 11, 2018

Inspection Overall Score: 44

Significant Findings:

Paint coating is in fair condition with some light rust around the base plate area.



Maintenance Issues:

N/A