

Howard County Traffic Signal Inspection Summary Report:

Signal Number: 035
Location: Guilford Rd. at Eden Brook
Inspection Date: May 1, 2018

Inspection Overall Score: 24

Significant Findings:

Poles and paint coating in good condition. SW Corner – ped push button has exposed wiring and conduit.



Maintenance Issues:

Damaged elbow into cabinet.

