


Howard County Traffic Signal Inspection Summary Report:

Signal Number: 038
Location: Guilford Rd. at Murray Hill Rd.
Inspection Date: May 1, 2018

Inspection Overall Score: 49

Significant Findings:

Poles are in overall fair condition. Paint coating is in fair condition, with considerable rusting behind the anchor nut caps. Recommend media blasting, prime, and re-paint.



Maintenance Issues:

Crosswalks and stop lines are in fair condition.