

## Howard County Traffic Signal Inspection Summary Report:

**Signal Number:** 049  
**Location:** Main Street at Ellicott Mills Rd.  
**Inspection Date:** May 24, 2018

**Inspection Overall Score:** 26

### Significant Findings:

Poles are in overall good condition. Paint coating is in fair condition with some areas of coating failure and rust forming. SE pole is buried in an embankment and could not be inspected.



### Maintenance Issues:

NW Corner – loose tightening nuts. Overgrowth needs to be trimmed away from this structure.