

Howard County Traffic Signal Inspection Summary Report:

Signal Number: 052
Location: Snowden River Parkway at McGaw Rd./Warehouse
Inspection Date: May 2, 2018

Inspection Overall Score: 8

Significant Findings:

New signal.



Maintenance Issues:

East Side – loose tightening nuts.