

Howard County Traffic Signal Inspection Summary Report:

Signal Number: 054
Location: Little Patuxent Parkway at Broken Land Parkway/Banneker
Inspection Date: April 11, 2018

Inspection Overall Score: 33

Significant Findings:

Poles are in overall fair condition. Paint coating is in overall fair condition with some areas of coating failure and rust beginning to form.



Maintenance Issues:

N/A