

Howard County Traffic Signal Inspection Summary Report:

Signal Number: 058
Location: Hickory Ridge Rd. at Martin Rd.?
Inspection Date: April 11, 2018

Inspection Overall Score: 28

Significant Findings:

Poles in overall good condition. SW Corner – pole has vehicle impact damage. Paint coating in fair condition with some areas of coating failure and rust beginning to form.



Maintenance Issues:

N/A