

## Howard County Traffic Signal Inspection Summary Report:

**Signal Number:** 060

**Location:** Stevens Forest Rd. at Kilimanjaro Rd.

**Inspection Date:** May 24, 2018

**Inspection Overall Score:** 26

### Significant Findings:

Poles in overall good condition. Paint coating in fair condition with some areas of coating failure and rust beginning to form.



### Maintenance Issues:

NE and SW Corners – loose tightening nuts.