Howard County Traffic Signal Inspection Summary Report:

Signal Number: 061

Location: Hickory Ridge Rd. at Sunny Spring Dr.

Inspection Date: April 12, 2018

Inspection Overall Score: 23

Significant Findings:

Poles in overall good condition. Paint coating is in fair condition with some areas of coating failure and rust beginning to form mainly on the mast-arms.





Maintenance Issues:

NE Corner – loose ped pole.