

Howard County Traffic Signal Inspection Summary Report:

Signal Number: 063
Location: Snowden River Parkway at Dobbin Rd./Dried Earth
Inspection Date: April 12, 2018

Inspection Overall Score: 26

Significant Findings:

Poles in overall good condition. Paint coating is in fair condition with some areas of coating failure and rust beginning to form mainly on the mast-arms.



Maintenance Issues:

South Leg Median – loose tightening nuts.
NE Corner – loose ped pole.
Several hand holes retaining water.