

Howard County Traffic Signal Inspection Summary Report:

Signal Number: 067
Location: Long Gate Parkway at Wheatfield Way
Inspection Date: May 15, 2018

Inspection Overall Score: 26

Significant Findings:

Poles in overall good condition. NW Corner has vehicle impact damage. Paint coating is in fair condition with some areas of coating failure and rust beginning to form.



Maintenance Issues:

NE Corner – loose tightening nuts.
SW Corner – loose ped pole.