

Howard County Traffic Signal Inspection Summary Report:

Signal Number: 071
Location: Guilford Rd. at S. Trotter Rd.
Inspection Date: May 24, 2018

Inspection Overall Score: 21

Significant Findings:

Galvanized poles in overall good condition. Some light surface rust around the base plates and mast-arm mounting plates.



Maintenance Issues:

SE Corner – bottom adaptor plate has loose bolts. Trim overgrowth from around the base of this structure.

