

## Howard County Traffic Signal Inspection Summary Report:

**Signal Number:** 082  
**Location:** Oakland Mills Rd. at Kilimanjaro Rd./Helen Dorsey  
**Inspection Date:** May 24, 2018

**Inspection Overall Score:** 21

### Significant Findings:

Poles are in overall good condition. Paint coating is in fair condition with some small areas of paint coating failure and surface rust beginning. Recommend clean, prime, and re-paint.



### Maintenance Issues:

NE, NW, and SE Corners – loose tightening nuts.  
Cabinet has ant infestation.  
Damaged electrical service conduit.

